No.: 42

Enclosure to National Report for (country): Germany

DETAILS OF INTERESTING LARGE CLAIMS 1999

Type of insurance:	M+BE LP(M) A	LOP (DSU)
	EAR CAR G	EE Other
Type of plant:	Wind mill generator piants	
Location:	worldwide	
Type of insured property: (see code No. 1 − 11)	process equipment,gears Date of	Loss: various in 1999
Manufacturer:	Flender AG Year of	manufacture: 1997/98
Damaged component:	bearings, pinions, greater wheels	
Cause of loss:	faulty design (+ manufacture)	
(see code No. 1 – 10) Type of loss:	breakdown	
Hours of operation:	within warranty period Duration of outage: 2 weks-3m.	
Sum insured:	206 Mio DM	
Claim amount (100 %): after subtraction of deductible:	paid ⊠ 8,025 Mio DM	estimated
	8,025 Mio DM	estimatedxclusion:
after subtraction of deductible:	8,025 Mio DM 885.000,- TDM Time e	
after subtraction of deductible: Deductible:	8,025 Mio DM 885.000,- TDM Time e operator S	xclusion:
after subtraction of deductible: Deductible: Detection of loss by: Which measures could	8,025 Mio DM 885.000,- TDM Time e operator inspection	xclusion: safety device other other
after subtraction of deductible: Deductible: Detection of loss by: Which measures could have prevented the damage: Loss prevention measures	8,025 Mio DM 885.000,- TDM Time e operator Sinspection Setter design + manufacture bigger bearings, modification of control of the control	xclusion: safety device other other
after subtraction of deductible: Deductible: Detection of loss by: Which measures could have prevented the damage: Loss prevention measures initiated:	8,025 Mio DM 885.000,- TDM Time e operator Sinspection Setter design + manufacture bigger bearings, modification of control of the control	xclusion: safety device other other
after subtraction of deductible: Deductible: Detection of loss by: Which measures could have prevented the damage: Loss prevention measures initiated:	8,025 Mio DM 885.000,- TDM Time e operator Sinspection Setter design + manufacture bigger bearings, modification of control of the control	xclusion: cafety device other other il cooling system,
after subtraction of deductible: Deductible: Detection of loss by: Which measures could have prevented the damage: Loss prevention measures initiated:	8,025 Mio DM 885.000,- TDM Time e operator Sinspection Setter design + manufacture bigger bearings, modification of control of the control	xclusion: safety device other other