

DETAILS OF INTERESTING CLAIM

No: DOIC 49

Type of Insurance:

LP

Description of damaged item:

Explosion in Odorous gas collection system

Cause of Loss:

(6) Explosion

Claim Cost:

Description of Incident and Loss Prevention Measures initiated:

An explosion had taken place in a blower in a malodorous gas collection system in a pulp mill. Possible exceeding of the lower explosion limit of the turpentine gas concentration in the air due to problems in the cooling system.

Outline the interesting or unusual aspects of this claim or problems experienced during settlement:

The reconstruction of the system was done in about two weeks including technical improvements and changes to prevent turpentine vents enter into the weak odorous gas collection system.



For more details refer to IMIA WGP 49, Page 39

http://www.imia.com/downloads/imia_papers/wgp49_2006.pdf