

## DETAILS OF INTERESTING CLAIM

No: DOIC 48

Type of Insurance:

LP

Description of damaged item:

Crack on Yankee dryer

Cause of Loss:

(2) Faulty material or workmanship

Claim Cost:

3 US\$ Mio

Description of Incident and Loss Prevention Measures initiated:

A 1050 mm crack in the surface of the Yankee dryer. At the start up of the paper machine, cold water was sprayed on the surface of the Yankee dryer, which caused thermal tension resulting in the crack.

Outline the interesting or unusual aspects of this claim or problems experienced during settlement:

The Yankee dryer was temporally fixed and replaced after 6 months.

