

Damage to a rail bed service machine due to broken frame structure

March 2007, Czechia

Insurance cover: Construction plant and machinery insurance

Occurrence, Cause of loss:

Due to an operational fault the operator let one of the lifted rails fall whilst the arms were moving into the rail bed. This caused the 40 meter frame structure of the machine to break and bend down to the rails.

Loss amount: EUR 300,000.

