

## DETAILS OF INTERESTING CLAIM

No: DOIC 42

### Type of Insurance:

M

### Description of damaged item:

Paper machine

### Cause of Loss:

(2) Faulty material or workmanship

### Claim Cost:

6,5 US\$ Mio

### Description of Incident and Loss Prevention Measures initiated:

A guide roll in the drying section of the paper machine broke and caused severe damage to five drying cylinders, twenty other guide rolls and the frame of the paper machine. The failure of the guide roll was caused by a small hole, which was used for fixing the weights, which balanced the guide roll.

### Outline the interesting or unusual aspects of this claim or problems experienced during settlement:

The paper machine was not working for eight days directly after the loss and an additional seven days were needed for installing the new drying cylinders and guide rolls.

For more details refer to IMIA WGP 49, Page 36

[http://www.imia.com/downloads/imia\\_papers/wgp49\\_2006.pdf](http://www.imia.com/downloads/imia_papers/wgp49_2006.pdf)